



Time measurement & Winding

Mechanical —

Accuracy

Measure within lapse of 10 ~ 60 minutes from full winding with ① posture.

Posture difference


Measure accuracy in below ① ~ ④ postures.

①Dial side up

26 o'clock side up

39 o'clock side up

④3 o'clock side up



■ To make full-winded

90 / 91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6T	Turn the crown 20 times

■ Winding direction



