9100 9110 9120 9122 9130 9132

πιγοτα



πιγοτα

Time measurement & Winding

Mechanical

Accuracy

Measure within lapse of $10 \sim 60$ minutes from full winding with ① posture.

Posture difference

Measure accuracy in below \bigcirc ~ \bigcirc postures.



To make full-winded

90 / 91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6Т	Turn the crown 20 times

Winding direction

