


<u>065-495</u> Attached Stem Ф18.5 SR616SW

Battery consumption could be minimum by pulling out the stem






7

Clearance

Original

Package

Clearance changes subject to the glass, case structure, and the length of the hand.



1,000pcs

<Battery Detector Function>
As warning second hand steps every 2 seconds
When battery becomes nearly empty.
(except for Cal. 9T22/15&9U15)

____ Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.



