


Ф28.2 SR621SW

7 Date Chi

CS nronograph Second


Chronograph Minute 24 Hour

Battery consumption could be minimum by pulling out the stem



Minute 0.40 Second 0.09 Small 0.02

Featured by Shock Detection



Original Package

500pcs

JS36 24 Cs Whigh Hand Ver. JS36

Time measurement

Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec

