

## JS00 JS10 JS20 JS50 JS55

# MIYOTA



## Featured by Shock Detection





### Time measurement


#### Accuracy

The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.

10 sec 10 sec 10 sec







Setting the Time

Set CHRONOGRAPH hands to reset

Press the button "A" to set the stopwatch second hand forward.

Press the button "B" to set the stopwatch second hand back.