



# Time measurement & Winding

### Mechanical —


## **Accuracy**

Measure within lapse of 10 ~ 60 minutes from full winding with ① posture.

#### Posture difference

Measure accuracy in below ① ~ ④ postures.

- ①Dial side up
- 26 o'clock side up
- 39 o'clock side up
- ④3 o'clock side up



### ■ To make full-winded

90 / 91	Turn the crown 40 times
82 / 8N	Turn the crown 40 times
6T	Turn the crown 20 times

## ■ Winding direction



